
BELZONA® SAVES LARGE SPLIT CASE PUMP

CUSTOMER

Coal Mine
British Columbia

APPLICATION DATE

1996

PROBLEM

The splitter of this cast iron Worthington split case sludge pump had broken away. The mine engineers had originally discarded the "Belzona fix" and insisted that a new cast section be made and welded into place. This was duly done at great expense. The new splitter was "fared in" with Belzona® 1311 and the pump internals coated. After operating for only a few weeks the pump started producing a rattling sound and on further inspection it was found that the new splitter had come adrift and the only thing keeping it in place was the Belzona® product used to "fare it in". Because there was no replacement, it was decided to go ahead with the Belzona® repair originally suggested but turned down.

PRODUCTS

Belzona® 1311 Ceramic R Metal
Belzona® 1321 Ceramic S Metal

SUBSTRATE

Cast iron

APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet CEP-1,3

BELZONA FACTS

After the 2nd repair using the Belzona solution the pump was returned to service and operated for 2 years at which stage it was removed to replace bearings and packings. An inspection revealed that the fabricated splitter was still in first rate condition and that coating applied to the pump to protect it from sliding abrasion was still in perfect condition. After the overall the pump was returned to service.

PHOTOGRAPHS

1. Photograph shows cast splitter missing. Note the evidence of the specialized welding.
2. Fabrication of new splitter in progress.
3. Fabrication of new splitter completed with the mesh area filled with Belzona® 1311 Ceramic R Metal.
4. Pump internals completely protected with 2 coats of Belzona® 1321 Ceramic S Metal.

