

## **BELZONA® 2000 SERIES PRODUCTS SEAL LEAKING VALVE FLANGE**

### **CUSTOMER**

Power Supply Company

### **APPLICATION DATE**

September 1992

### **PROBLEM**

The gasket seal had failed and needed replacement. This would have required draining the tank so that the valve could be removed.

### **PRODUCTS**

Belzona® 2211 MP Hi-Build Elastomer

### **SUBSTRATE**

Steel

### **APPLICATION METHOD**

Application carried out in accordance with a modified version of Belzona® Know-How Leaflet VPF-1

### **BELZONA FACTS**

Repair Completed in Just 2 Hours using Belzona Elastomers. A Conventional repair would have cost many thousands of dollars to drain, store and re-fill the transformer oil tank.

### **PHOTOGRAPHS**

1. View of transformer
2. Application in progress
3. Completed application

