
BELZONA® REBUILDS CORRODED STEEL DOOR FRAMES

CUSTOMER

Recreation Facility
Qualicum Beach, BC

APPLICATION DATE

August 2004

PROBLEM

Bottoms of steel door frames had corroded away as a result of constantly being in contact with pool water.

PRODUCTS

Belzona® 4141 Magma Build
Belzona® 3921 GSC Conditioner

SUBSTRATE

Steel / Concrete

APPLICATION METHOD

Application carried out in accordance with a modified version of Belzona® Know-How Leaflet FPA

BELZONA FACTS

This application had been done at another facility with good success.

PHOTOGRAPHS

1. View of one of the many corroded door frames with the bottom section cut away.
2. Bottom section rebuilt with Belzona® 4141 Magma Build
3. Repaired area repainted white.

