



# KNOW-HOW *In Action*

BC KHIA # 002

---

## BELZONA® FPA-8 NON-SLIP SAFETY SYSTEM

---

### CUSTOMER

REGIONAL HOSPITAL  
British Columbia, Canada

### APPLICATION DATE

On going applications since 1995

### PROBLEM

Non-slip safety system required in hospital dish washing and kitchen floors as soapy water and cooking grease created a continuous safety hazard for the kitchen personnel.

### PRODUCTS

Belzona® FPA-8 Non-Slip Safety System

### SUBSTRATE

Quarry tile

### APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet FPA-8

### BELZONA FACTS

Original test patch, installed in 1995 along with the main application remained in service with no maintenance till 2002 when entire area was revamped and a new floor installed. Whilst the new floor has non-slip qualities built into the surface it is felt by the hospital staff that this will diminish over time and that a Belzona FPA-8 Non-slip Safety System will eventually be installed over the top of it. The hospital staff appreciated the psychological benefits of the Belzona system – High visibility – easy to see where system begins and ends. Unlike non-slip floor coatings the Belzona system also gives the staff visible proof that their safety concerns have been addressed in a positive way.

### PHOTOGRAPHS

1. View of preparation in progress
2. Application in progress.
3. Completed application

