



# KNOW-HOW *In Action*

BC KHIA #062

---

## BELZONA® SEALS LEAKING HOSPITAL CONCRETE ENTRANCE CANOPY

---

### CUSTOMER

HOSPITAL  
North Vancouver, British Columbia, Canada

### APPLICATION DATE

August 1995

### PROBLEM

This complex concrete roof structure had presented sealing problems since it was constructed. The asphalt roofing material had been replaced a number of times over the years without any long term success.

### PRODUCTS

Belzona® 3111 Flexible Membrane

### SUBSTRATE

Asphalt roofing membrane and concrete.

### APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflets RPA-8

### BELZONA FACTS

Using Belzona® eliminated the need for repetitive sealing work with no additional maintenance work over the past 8 years. Another advantage was that the previous roofing material could be left in place and the Belzona product applied over the top of it without detriment.

### PHOTOGRAPHS

1. General view of roof with application in progress.
2. Completed application

