

## BELZONA® RESURFACES ENTRANCE TO PARKING GARAGE

### CUSTOMER

PROPERTY MANAGEMENT COMPANY  
Parking Garage  
Prince George, BC

### APPLICATION DATE

August 1997

### PROBLEM

Entrance to parking garage had become badly spalled.

### PRODUCTS

Belzona® 4131 Magma Screed

### SUBSTRATE

Concrete

### APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet RPA-1

### BELZONA FACTS

Using Belzona® allowed the area to be resurfaced without having to jack hammer the concrete out to provide space for a standard concrete pour of a few inches. This repair is in a cold climate and is subjected to freeze thaw cycles as well as deicing chemicals. The product stands up to both extremely well and has required no further attention to date.

### PHOTOGRAPHS

1. View of surface preparation in progress
2. Application of Belzona® 4131 in progress
3. Completed application (Taken after 4 years in service)

