
BELZONA® REBUILDS KITCHEN EXPANSION JOINTS

CUSTOMER

HOTEL
Vancouver, BC



APPLICATION DATE

February 2003

PROBLEM

Customer was in the process of refurbishing their banquet kitchen. The original material had sagged causing a tripping hazard. To obviate this the joint was covered over with a stainless steel metal strip which also proved to be unsatisfactory. The refurbishment required that the joint be covered by the new sheet form floor covering. As a result of this the joint needed to be cast level with the existing floor.

PRODUCTS

Belzona® 2221 MP Fluid Elastomer

SUBSTRATE

Concrete / tiles

APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet FPA-6

BELZONA FACTS

Because of the non-shrink properties of the Belzona material the customer could be assured that the joint could be overlaid without any future sagging concerns. An additional advantage was the quick set up time which allowed the flooring company to cover the joint after 24 hours. Joints similar to this one have been in service in BC for over 13 years without the need for any repair or refurbishment.

PHOTOGRAPHS

1. View of exposed expansion joint with preparation underway.
2. Pouring of joint in progress.
3. Completed application with floor leveled off and new flexible expansion joint cast.

