

BELZONA® REPLACES WORN OUT EXPANSION JOINTS

CUSTOMER

PROPERTY MANAGEMENT COMPANY
Burnaby, BC



APPLICATION DATE

December 2003

PROBLEM

Original patented extruded expansion joint rubber insert had developed cracks and tears compromising safety. These inserts are not readily available. This necessitates the removal and replacement of the entire aluminum extrusion, a long and lengthy procedure.

PRODUCTS

Belzona® 2221 MP Fluid Elastomer

SUBSTRATE

Aluminum

APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet FPA-6

BELZONA FACTS

The use of Belzona® 2221 MP Fluid Elastomer allows the insert to be cast in place without the need to remove or replace the aluminum edging resulting in minimal disruption to shopping mall traffic.

PHOTOGRAPHS

1. View of preparation in progress and old rubber insert removed
2. Application in progress.
3. Completed application

