
BELZONA® REPAIRS DAMAGED STEPS

CUSTOMER

Community Center
Burnaby, BC

APPLICATION DATE

June 2005

PROBLEM

The customer was looking to repair selected spalled areas on steps without having to resurface them entirely.

PRODUCTS

Belzona® 4131 Magma Screed.

SUBSTRATE

Concrete

APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet FPA-1

BELZONA FACTS

The use of Belzona 4131 Magma Screed provided a relatively close match to the original

PHOTOGRAPHS

1. View of spalling stair treads.
2. Close up of repair.
3. View of repaired stairway

