
BELZONA® PROTECTS END COVERS

CUSTOMER

PULP MILL
Kamloops, BC.

APPLICATION DATE

August 1998

PROBLEM

End covers were suffering from bi-metallic corrosion and severe pitting.

PRODUCTS

Belzona® 1311 Ceramic R Metal
Belzona® 1391 HT Ceramic

SUBSTRATE

Mild steel.

APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflets
HEX-2

BELZONA FACTS

Using Belzona® eliminated the need to replace the units.

PHOTOGRAPHS

1. View of end covers after blasting
2. Repairs to flange faces using plexiglas as a former.
3. Completed application with insides protected with Belzona® 1391.

