
BELZONA® REBUILDS CORRODED END COVERS

CUSTOMER

OIL REFINERY
Vancouver, BC

APPLICATION DATE

August 1988

PROBLEM

Bi-metallic corrosion had eroded much of the metal making it difficult to effect a good seal along the division bars reducing efficiency.

PRODUCTS

Belzona® 1311 Ceramic R Metal
Belzona® 1321 Ceramic S Metal

SUBSTRATE

Mild steel

APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet HEX-2

BELZONA FACTS

Using Belzona® eliminated the need to fabricate new end covers. Coating the metal surface also reduced the chance of corrosion.

PHOTOGRAPHS

1. View of corroded end plate
2. Repairs to eroded and damaged areas in progress.
3. Completed application

