
BELZONA® PROTECTS AIR HANDLING UNITS FROM CORROSION

CUSTOMER

Property Management Company
North Vancouver, BC.



APPLICATION DATE

May 2005

PROBLEM

The galvanized coating on the original sheet metal was starting to show signs of corrosion

PRODUCTS

Belzona® 5811 Immersion Grade

SUBSTRATE

Steel sheet

APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet HEX-3

BELZONA FACTS

The combination of the correct metal surface preparation, attention to detail and a to quality coating has insured that these air handling units will remain in service for many years to come

PHOTOGRAPHS

1. View of the BAC air handling unit.
2. Preparation of the inner metal surfaces in progress.
3. Final preparation of the inner metal surfaces in progress.
4. Application of 2 coats of Belzona® 5811 Immersion Grade in progress.

