

---

## NON MARKING TRANSFER ROLLS IN SAWMILL

---

### CUSTOMER

SAW MILL  
British Columbia, Canada

### APPLICATION DATE

October 2001

### PROBLEM

The mild steel transfer rolls were leaving black rub marks on the lumber. This was an unacceptable condition for their customers.

### PRODUCTS

Belzona® 1341 Supermetalgilde

### SUBSTRATE

Mild steel

### APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet SHM-12

### BELZONA FACTS

Marked lumber had developed into a major problem at the mill. An application of Belzona® 1341 Supermetalgilde to all the transfer rolls (21) ensured that the planed lumber remained clean and unmarked while it was been processed. This saved the mill many hours in re-sanding time

### PHOTOGRAPHS

1. View of preparation in progress
2. Close up of application in progress.
3. Completed application

