
BELZONA® REBUILDS BAND SAW SLIDE

CUSTOMER

LUMBER PRODUCER
Vancouver Island, BC.

APPLICATION DATE

August 1998

PROBLEM

The constant attack from saw dust had worn away about 12 inches of the bandsaw slide causing it to jam.

PRODUCTS

Belzona® 1311 Ceramic R Metal

SUBSTRATE

Cast iron

APPLICATION METHOD

Application carried out in accordance with a modified version of Belzona® Know-How Leaflets GSS-5

BELZONA FACTS

Using Belzona® eliminated the need to dismantle equipment as repair could be done in place saving many hours of downtime and lost production.

PHOTOGRAPHS

1. View of worn band saw slide area.
2. Completed repair.

