
BELZONA® REBUILDS KEY WAY AND SAVES DOWNTIME

CUSTOMER

LUMBER MANUFACTURER
British Columbia, Canada

APPLICATION DATE

August 1996

PROBLEM

Keyway had become badly worn and sloppy.

PRODUCTS

Belzona® 1111 Super Metal

SUBSTRATE

Steel

APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet MPT-4

BELZONA FACTS

This repair was completed without having to remove the shaft resulting in a major saving in downtime costs

PHOTOGRAPHS

1. View of damaged keyway
2. Keyway reset in Belzona 1111 Super Metal.
3. Drive flange use to locate and position keyway correctly.

