

---

## BELZONA® REPAIRS DAMAGED SHAFT SAVING DOWNTIME

---

### CUSTOMER

Lumber Mill  
Penticton, BC

### APPLICATION DATE

1999

### PROBLEM

Seized bearing had worn shaft

### PRODUCTS

Belzona® 1111 Super Metal

### SUBSTRATE

Mild steel

### APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet MPT-2

### BELZONA FACTS

Belzona® 1111 Super Metal is dimensionally stable enabling the shaft to be reformed and repaired using a simple mold. This eliminated the need for dismantling saving many hours of downtime.

### PHOTOGRAPHS

1. View of damage shaft
2. Repair in progress with mold in place
3. Mold removed and ready for reassembly.

