
BELZONA® REBUILDS PLANER HEAD THROAT

CUSTOMER

Saw Mill
Nanaimo, BC.

APPLICATION DATE

May 2005

PROBLEM

A hole had worn through the cast iron of this planer allowing wood shavings to be blown around and causing a breathing hazard

PRODUCTS

Belzona® 1811 Ceramic Carbide

SUBSTRATE

Cast Iron

APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet

BELZONA FACTS

Rebuilding with Belzona made for a simple straightforward repair eliminating the need to weld. Similar repairs completed at other mills have proved to be extremely effective, lasting many years.

PHOTOGRAPHS

1. General view of planer head.
2. View of hole.
3. Not the prettiest application but nevertheless rebuilt and already in service..

