
BELZONA® REBUILDS AND PROTECTS ONBOARD SEAWATER STRAINER

CUSTOMER

INTERNATIONAL SHIPPING COMPANY
Vancouver, BC

APPLICATION DATE

August 2000

PROBLEM

Bi-metallic corrosion had eroded much of the metal adjoining the welds. The vessel was also constructed of a very poor grade mild steel which resulted in massive losses of metal

PRODUCTS

Belzona® 1311 Ceramic R Metal
Belzona® 1321 Ceramic S Metal

SUBSTRATE

Mild steel.

APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflets TCC
1

BELZONA FACTS

The use of Belzona® has extended the life of this vessel.

PHOTOGRAPHS

1. View of vessel preparation in progress.
2. Application of 1st coat of Belzona®1321 to wet out the metal surface.
3. Repairs to eroded and damaged areas in progress.
4. Application complete.

