
BELZONA® REBUILDS AND PROTECTS KORT NOZZLE

CUSTOMER

TUG BOAT OPERATOR
Vancouver, BC

APPLICATION DATE

August 1995

PROBLEM

Bi-Metallic erosion

PRODUCTS

Belzona® 1311 Ceramic R Metal
Belzona® 1341 Supermetalgilde

SUBSTRATE

Mild steel

APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet SOS-1,2

BELZONA FACTS

This was the 4th vessel belonging to this operator that had been rebuilt and protected with Belzona® products.

PHOTOGRAPHS

1. View of tug boat and kort nozzle removed
2. Application of 1st Coat of 1341 completed with application of 2nd coat in progress.
3. Application of 2nd coat completed.
4. Nozzle reinstalled. Plug areas rebuilt with Belzona®1311 prior to application of Belzona®1341.

