

---

## BELZONA® PROTECTS RUDDERS FROM CORROSION & CAVITATION

---

### CUSTOMER

Ferry Operator  
Victoria, BC

### APPLICATION DATE

May 2003

### PROBLEM

The rudders suffer from serious cavitation problems.

### PRODUCTS

Belzona® 1311 Ceramic R Metal  
Belzona® 1341 Supermetalglide

### SUBSTRATE

Mild Steel

### APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet SOS 1,2

### BELZONA FACTS

Application of Belzona® 1341 Supermetalglide will help reduce the effects of cavitation between dry dockings.

### PHOTOGRAPHS

1. Rudder after grit blasting
2. Excessively cavitated areas are rebuilt with Belzona® 1311 before being over coated with Belzona® 1341 Supermetalglide.
3. Final coat of Belzona® 1341 Supermetalglide (Grey) applied and force cured with heat lamps to meet deadline.

