

---

## BELZONA® 1341 SUPERMETALGLIDE PROTECTS RUDDERS

---

### CUSTOMER

Dry Dock  
Vancouver, BC

### APPLICATION DATE

February 2006

### PROBLEM

Rudders were showing sever metal loss in areas where cavitation attack prevalent .

### PRODUCTS

Belzona® 1311 Ceramic R Metal  
Belzona® 1321 Ceramic S Metal  
Belzona® 1341 Supermetalgilde

### SUBSTRATE

Cast / Steel

### APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet SOS-1/2

### BELZONA FACTS

The use of Belzona for these types of repairs eliminates the need to weld with all its associated problems. The rebuild process also reduces the time required to complete a repair of this kind.

### PHOTOGRAPHS

1. View of one of the many badly cavitated areas on the two rudders
2. Rebuilding of eroded areas in progress
3. Application of 1<sup>st</sup> coat of Belzona 1341 Supermetalgilde in progress
4. Application of 2<sup>nd</sup> coat of Belzona 1341 Supermetalgilde completed

