
BELZONA® REPAIRS CABLE REINFORCED CONVEYOR BELT

CUSTOMER

COAL MINE
British Columbia, Canada

APPLICATION DATE

August 1996

PROBLEM

Cable stayed belt would develop cracks over a period of time.

PRODUCTS

Belzona® 2311 SR Elastomer

SUBSTRATE

Rubber

APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet SHM-1

BELZONA FACTS

Because of its rapid set up time coupled with as quick development of mechanical strength, Belzona® 2311 SR Elastomer allowed repairs to be made to the belt during unscheduled or short shut downs

PHOTOGRAPHS

1. View of preparation in progress
2. Close up of one of the repair areas.
3. Completed application

