
BELZONA® REBUILDS MAIN PIVOT SHAFT ON SITE

CUSTOMER

COAL MINE
British Columbia, Canada

APPLICATION DATE

August 1996

PROBLEM

Original bearing had badly worn the main pivot shaft of this excavating crane

PRODUCTS

Belzona® 1111 Super Metal

SUBSTRATE

Steel

APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet MPT-2

BELZONA FACTS

This application was completed in the field without having to bring the equipment back into the shop saving many hours of downtime. The repair was also completed in less time than would have been required for a conventional weld and machine type repair.

PHOTOGRAPHS

1. View of preparation in progress
2. Application in progress.
3. Completed application with mold still in place. Mold removed after material had set up leaving a remolded bearing area.

