

---

## BELZONA® 2200 SERIES ELASTOMERS REPAIR CUT IN TIRE

---

### CUSTOMER

Coal mine

### APPLICATION DATE

June 1995

### PROBLEM

Tire on earthmoving equipment had been badly damaged.

### PRODUCTS

Belzona® 2211 MP Hi-Build Elastomer  
Belzona® 2911 QD Conditioner

### SUBSTRATE

Rubber

### APPLICATION METHOD

Application carried out in accordance with a modified version of Belzona® Know-How Leaflet SHM-1

### BELZONA FACTS

Quick repairs to this type of damage prevents further damage to the underlying reinforcing plies allowing the equipment to continue operating until a scheduled downtime

### PHOTOGRAPHS

1. View of equipment and the extent of the damaged area
2. Surface around the damaged area prepared and coated with Belzona® 2911 QD Conditioner.
3. Damaged area sealed and rebuilt with Belzona® 2211 MP Hi-Build Elastomer.

