

---

## BELZONA® REBUILDS WORN CAT D9 SPLINESHAFT ASSEMBLY

---

### CUSTOMER

Mining operation  
Tumbler Ridge, BC.

### PROBLEM

The main drive spline on D-9 cat had worn loose over many years of service.

### PRODUCTS

Belzona® 1111 Super Metal

### SUBSTRATE

Steel

### APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How MPT-5

### BELZONA FACTS

With applications of Belzona®, the option to disassemble can be done when required.

### PHOTOGRAPHS

1. View of worn spline shaft assembly.
2. Belzona 1111 Super Metal applied to worn splines
3. Components reassembled.
4. The main framework that the Spline assembly will be bolted to.

