
BELZONA® SEALS TRANSFORMER BUSS BOX

CUSTOMER

ELECTRICAL UTILITY COMPANY
Vernon, BC

APPLICATION DATE

August 2000

PROBLEM

Oil was seeping into electrical buss box causing a disruption in electrical supply.

PRODUCTS

Belzona® 2221 MP Fluid Elastomer.

SUBSTRATE

Mild steel and brass electrical connectors.

APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflets
GSS-4

BELZONA FACTS

Using Belzona® eliminated the need to have the equipment taken out of service
for a prolonged period.

PHOTOGRAPHS

1. View of box after grit blasting
2. Belzona® 2221 MP Fluid Elastomer poured into the electrical box sealing
around all connection points.

