
BELZONA® SEALS INSULATOR LEAKS

CUSTOMER

Power Generation Facility
Jordan River, BC

APPLICATION DATE

August 2003

PROBLEM

Insulators were leaking oil.

PRODUCTS

Belzona® 2121 D&A Hi-Coat Elastomer

SUBSTRATE

Porcelain and Aluminum

APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet GSS-3

BELZONA FACTS

Belzona products have been used for many of these types of sealing applications over many years with good success.

PHOTOGRAPHS

1. Surface preparation in progress.
2. Surface preparation by grit blasting completed.
3. Completed application – not pretty but effective nevertheless.

