

BELZONA® SEALS SF₆ LEAKS AT HYDROELECTRIC POWER STATION

CUSTOMER

Power Generating Dam
Mica Creek, BC

APPLICATION DATE

1993

PROBLEM

Sulfur Hexafluoride gas was leaking from the joints of the system requiring regular refilling..

PRODUCTS

Belzona® 2211 MP Hi-Build Elastomer

SUBSTRATE

Steel

APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet GSS-4

BELZONA FACTS

This application has been in service for many years with only minor repairs required. TOTAL TIME IN SERVICE - 13 YEARS

PHOTOGRAPHS

1. Belzona® 2211 was injected into the gap between the 2 flanges.
2. Application shown in #1 completed.
3. Another flange sealed.

