
BELZONA® 2000 SERIES PRODUCTS SEAL GAS LEAK

CUSTOMER

Power Supply Company

APPLICATION DATE

June 1998

PROBLEM

SF6 Gas was leaking through the porcelain bushing saels .

PRODUCTS

Belzona® 2211 MP Hi-Build Elastomer

SUBSTRATE

Porcelain

APPLICATION METHOD

Application carried out in accordance with a modified version of Belzona® Know-How Leaflet VPF-11

BELZONA FACTS

A fast and economical repair.

PHOTOGRAPHS

1. View of sub station
2. Preparation and repair under way.
3. Completed repair

