
BELZONA® REBUILDS DAMAGED GRANITE ROLL

CUSTOMER

PULP & PAPER MILL
QUEBEC, CANADA

APPLICATION DATE

August 2001

PROBLEM

The edge of the granite roll had been damaged causing production problems.

PRODUCTS

Belzona® 1211E Metal

SUBSTRATE

Granite and steel

APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet

BELZONA FACTS

This repair was completed using a Belzona quick setting emergency repair compound allowing the repair to be completed in the scheduled 8 hour shut down.

PHOTOGRAPHS

1. View of damaged roll
2. Repair in progress.
3. Completed application before masking tape removed.

