
BELZONA® REBUILDS BRASS PLATED SEAL SURFACE

CUSTOMER

PULP & PAPER OPERATION
Powell River, BC.

APPLICATION DATE

MAY 2000

PROBLEM

Bronze overlay had started to delaminate from the base metal.

PRODUCTS

Belzona® 1131 Bearing Metal

SUBSTRATE

Cast iron and brass

APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet MPT-1

BELZONA FACTS

The use of Belzona for this application saved many days of downtime.

PHOTOGRAPHS

1. View of damage
2. Close up of area after repair

