
BELZONA® 1111 SUPER METAL SAVES COUCH ROLL

CUSTOMER

PULP AND PAPER
Campbell River, BC.

APPLICATION DATE

August 2000

PROBLEM

A foreign object had badly damaged the inside of the couch roll.

PRODUCTS

Belzona® 1111 Super Metal

SUBSTRATE

Bronze

APPLICATION METHOD

Application carried out in accordance with a modified version of Belzona® Know-How Leaflet GSS-8

BELZONA FACTS

The use of the Belzona® repair procedure enabled the mill to repair the damaged area of the couch roll on site in less than 2 days. The alternative would have required shipping the roll to Vancouver incurring tens of thousands of dollars in extra costs for shipping, welding and machining. This repair is still in service 6 years later

PHOTOGRAPHS

1. View of damaged couch roll with repair area masked off ready for rebuilding
2. Damaged area rebuilt and plastic forms wedged in place in preparation for drilling.
3. Holes being re-drilled from the outside.
4. View of partially completed area.

