
BELZONA® REBUILDS BEARING SURFACES ON A PAPER MACHINE DRIVE UNIT

CUSTOMER

Pulp and Paper Company
Port Alberni, BC.

APPLICATION DATE

July 2000

PROBLEM

The bearing surfaces of a paper machine main drive unit was badly damaged and starting to cause "gear lash" problems.

PRODUCTS

Belzona® 1111 Super Metal

SUBSTRATE

Mild steel

APPLICATION METHOD

Application carried out in accordance with modified version of Belzona® Know-How Leaflet MPT-3

BELZONA FACTS

This repair provides a quick and effective repair saving many hours of downtime

PHOTOGRAPHS

1. View of damaged bearing cap.
2. Surface preparation underway.
3. Completed repair

