
BELZONA® REBUILDS BEARING FIT ON PAPER MACHINE DRIVE

CUSTOMER

Pulp & Paper
Port Alberni, BC.

APPLICATION DATE

2001

PROBLEM

Worn bearing fit causing gear lash problems.

PRODUCTS

Belzona® 1321

SUBSTRATE

Cast Iron

APPLICATION METHOD

A modified version of MPT-7 using injection techniques.

BELZONA FACTS

There is a long history at this facility using Belzona on both bearing fits and journals without any failures.

PHOTOGRAPHS

1. Fit area has been ground out with a die grinder.
2. Mold was shrunk with nitrogen to ensure easy fit without damaging release agent when put in place. It is still warming up at this point.
3. Finished bearing fit, another absolutely perfect fit, done in less time than it would have taken to disassemble the housing.

