

---

## BELZONA® SAVES & PROTECTS VACUUM

---

### CUSTOMER

PULP & PAPER OPERATION  
Nanaimo, BC

### APPLICATION DATE

February 2000

### PROBLEM

Massive erosion of metal had rendered vacuum pump ineffective.

### PRODUCTS

Belzona® 1111 Super Metal  
Belzona® 1341 Supermetalglide

### SUBSTRATE

Steel

### APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet CEP-3,5

### BELZONA FACTS

Rebuilding with Belzona® allowed the vacuum pump to be repaired in house saving both downtime and maintenance dollars. The unit was also protected internally to prevent the problem from re-occurring.

### PHOTOGRAPHS

1. View of eroded casing
2. Close up showing extent of metal loss.
3. Completed application

