
BELZONA® SAVES BRINE PUMP FROM THE SCRAP HEAP

CUSTOMER

RECREATION CENTER – HOCKEY RINK
British Columbia, Canada

APPLICATION DATE

August 2002

PROBLEM

Pump used to pump brine solution was slated for the scrap heap

PRODUCTS

Belzona® 1321 Ceramic S Metal
Belzona® 5811 Immersion Grade

SUBSTRATE

Cast Iron

APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet CEP-1,2,3

BELZONA FACTS

The use of Belzona repair procedures enable the facility to rebuild the pump and return it to service saving on replacement costs.

PHOTOGRAPHS

1. View of corroded pump body
2. Completed application with inside repaired and coated with Belzona® 1321 and the outside protected with Belzona® 5811 Immersion Grade

