

---

## BELZONA® PUMP SPLITTER REBUILD

---

### CUSTOMER

Mining Company  
Tumbler Ridge, BC

### APPLICATION DATE

1996

### PROBLEM

Cast iron pump splitter had broken away.

### PRODUCTS

Belzona® 1311 Ceramic R Metal  
Belzona® 1321 Ceramic S Metal

### SUBSTRATE

Cast iron

### APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet CEP-1

### BELZONA FACTS

Pump casing had already been consigned to the scrap yard when Belzona repair solution was accepted.

### PHOTOGRAPHS

1. View of missing splitter.
2. Reinforcement in place for construction of new fabricated splitter using Belzona 1311 Ceramic R Metal.
3. Rebuilt splitter.

