

---

## BELZONA® SEALS GAP BETWEEN WALL AND ACCESS RAMP

---

### CUSTOMER

CITY OF BURNABY  
Recreation Center

### APPLICATION DATE

September 2002

### PROBLEM

The caulking between the walls and ramp base needed to be replaced on a regular basis to prevent water from entering into the area below.

### PRODUCTS

Belzona® 3111 Flexible Membrane

### SUBSTRATE

Concrete

### APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet RPA-1

### BELZONA FACTS

Belzona® 3111 Flexible Membrane was used to create a flexible flashing between the wall and floor.

### PHOTOGRAPHS

1. View of joint to be sealed
2. Application of 1<sup>st</sup> coat of Belzona 3111 Flexible Membrane in progress along with reinforcement sheet.
3. Completed application

