

BELZONA® 3111 PROTECTS STAIRCASE FROM CORROSION

CUSTOMER

RECREATION CENTER
Trail, BC.

APPLICATION DATE

June 2003

PROBLEM

The wrought iron stair rail was a constant source of unsightly corrosion leading to unsightly staining. Additionally the underside coating required repainting every year.

PRODUCTS

Belzona® 3111 Flexible Membrane
Belzona® 4111 Magma Quartz
Belzona® 5122 Clear Cladding

SUBSTRATE

Reinforced concrete

APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet FPA-1 and RPA-1

BELZONA FACTS

The normal Belzona attention to detail by analyzing the cause of the problem and dealing directly with it will ensure that this structure remains aesthetically pleasing and be free of the many chronic corrosion problems that have needed attention every year during the pools annual maintenance shut down.

PHOTOGRAPHS

1. View of structure showing the corrosion problem
2. Surface preparation via wet sand blasting in progress.
3. Completed application

