

BELZONA® REDUCES COST OF EXPANSION JOINT REFURBISHMENT

CUSTOMER

Public Recreation Facility
Burnaby, BC

APPLICATION DATE

March 1996

PROBLEM

Deterioration of expansion joints were a continuous problem. Facility would budget for the replacement of 25-30% of total pool joints each shutdown.

PRODUCTS

Belzona® 2211 MP Hi-Build Elastomer
Belzona® 2211 MP Fluid Elastomer

SUBSTRATE

Concrete and ceramic tile

APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet FPA-6

BELZONA FACTS

After the installation of the Belzona® Elastomers annual refurbishment of expansion joints was eliminated. In the harshest area –hot tub – the Belzona® product lasted 4 years. Other areas have lasted 7 years without the need for additional maintenance saving the facility time and maintenance dollars.

PHOTOGRAPHS

1. General view of facility
2. View of the hot tub
3. View of completed expansion joints.

