

BELZONA® REDUCES COST OF EXPANSION JOINT REFURBISHMENT

CUSTOMER

Public Recreation Facility
Williams Lake, BC

APPLICATION DATE

March 1997

PROBLEM

Deterioration of expansion joints were a constant problem. This facility would budget annually for the replacement of expansion joint material. This repetitive repair and refurbishment work was creating a constant drain on the annual maintenance budget.

PRODUCTS

Belzona® 2211 MP Hi-Build Elastomer
Belzona® 2211 MP Fluid Elastomer

SUBSTRATE

Concrete and ceramic tile

APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet FPA-6

BELZONA FACTS

After the installation of the Belzona® Elastomers annual refurbishment of the expansion joints was eliminated. These joints are now 7 years old and still providing protection to the joints.

PHOTOGRAPHS

1. General view of deteriorated expansion joint
2. Application in progress
3. View of completed expansion joint section.

