

BELZONA® REBUILD AND PROTECTS SPALLED CONCRETE STAIRS

CUSTOMER

Municipal Recreation Center
Burnaby, BC.

APPLICATION DATE

1998

PROBLEM

Spiral concrete staircase was becoming badly spalled and cracked creating a safety hazard.

PRODUCTS

Belzona® 4131 Magma Screed
Belzona® 5122 Clear Cladding

SUBSTRATE

Concrete

APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet FPA-1

BELZONA FACTS

The Belzona product was able to repair and seal all cracks as well as resurface the spalled areas. After completion the whole area was protected with Belzona® 5122 Clear Cladding to impede further water ingress.

PHOTOGRAPHS

1. Preparation in progress
2. Surfaces coated with Belzona® 4911 TX Conditioner
3. Completed repairs with front of stairs refaced. With minimal repairs over the next few years a decision was made to reface all the stairs with Belzona® 4131 to improve the visual aspects of the stairs.

