
BELZONA® RESURFACES CONCRETE AT ENTRANCE TO ICE RINK

CUSTOMER

Ice Arena
Williams Lake, BC

APPLICATION DATE

1999

PROBLEM

Concrete at the entrance to the ice rink had become badly spalled making it difficult for the Zamboni to get on and off the ice sheet.

PRODUCTS

Belzona® 4111 Magma Quartz

SUBSTRATE

Concrete

APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet FPA-1

BELZONA FACTS

Because of temperature variations all products previously used had failed within a year. This repair is still in service some 5 years later.

PHOTOGRAPHS

1. View of damaged area.
2. Completed application

