
BELZONA® RESURFACES LEAKING POOL SUMP

CUSTOMER

University Swimming Pool
Victoria, BC

APPLICATION DATE

August 2004

PROBLEM

This was one of the many points from which the pool was losing water

PRODUCTS

Belzona® 4111 Magma Quartz

SUBSTRATE

Concrete

APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet FPA-1

BELZONA FACTS

The use of Belzona® allowed the sides and bottom of the drain to be resurfaced. The non-porous nature of the product ensured a water tight solution.

PHOTOGRAPHS

1. View of the degraded concrete sump.
2. View of one of the worst areas of sump
3. Resurfaced sump

