
BELZONA® GIVES POOL MAINTENANCE OFFICE A LIFT

CUSTOMER

Recreation Center
Burnaby, BC.

APPLICATION DATE

April 2005

PROBLEM

Maintenance office floor had become badly stained over the years and was in need of a cosmetic uplift.

PRODUCTS

Belzona® 5231 SG Laminate

SUBSTRATE

Concrete

APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet FPA-3

BELZONA FACTS

The quick drying characteristics of the product allowed the project to be completed in 8 hours. .

PHOTOGRAPHS

1. Preparation of floor surface in progress with Vacublast unit.
2. Preparation and masking completed.
3. Two coats of Belzona® 5231 SG Laminate applied

