
BELZONA® 4000 SERIES PRODUCTS REFURBISH RED TILES

CUSTOMER

Recreation Center
Burnaby, BC

APPLICATION DATE

March 2005

PROBLEM

The red glazing on tiles used to mark the depth of the pool was disbanding and looking unsightly .

PRODUCTS

Belzona® 4911 TX Conditioner
Belzona® 4411 Granogrip Red

SUBSTRATE

Ceramic tile

APPLICATION METHOD

Application carried out in accordance with a modified version of Belzona® Know-How Leaflet FPA-4

BELZONA FACTS

The use of Belzona 4411 Granogrip had worked well in other areas of the facility providing more than 4 years of service without maintenance.

PHOTOGRAPHS

1. The original red glazing was scraped off before the tile surfaces were ground to provide a smooth porous surface.
2. The ground surfaces were first conditioned with Belzona 4911 TX Conditioner.
3. Application of 1st coat of Belzona 4411 Granogrip (Red).
4. Completed application

