

BELZONA® 4411 GRANOGRIP USED TO REPLACE FADED POOL MARKINGS

CUSTOMER

Recreation Center
Burnaby, BC

APPLICATION DATE

March 2006

PROBLEM

The green markings around the edge of the sitting area in the hot tub had eroded away over a period of years and needed to be replaced as it was a safety issue.

PRODUCTS

Belzona® 4411 Granogrip (Tinted green with a suitable epoxy tinter)

SUBSTRATE

Ceramic tile

APPLICATION METHOD

Application carried out in accordance with a modified version of Belzona® Know-How Leaflet FPA-4

BELZONA FACTS

The only other permanent repair was to replace the tiles with new ones. Other applications at the pool using this product had thus far proved to be very successful.

PHOTOGRAPHS

1. The strip along the edge of the tile was ground to expose a porous surface and masked off to ensure a neat finish.
2. Application in progress.
3. Completed application.

