
BELZONA® MEMBRANE PROTECTS COLUMNS FROM CORROSION

CUSTOMER

Recreation Center
Burnaby, BC.

APPLICATION DATE

1998

PROBLEM

Because of the constant dampness and high humidity corrosion between the mild steel base plates and the concrete plinths was a perennial problem.

PRODUCTS

Belzona® 3111 Flexible Membrane

SUBSTRATE

Mild steel and concrete

APPLICATION METHOD

Application carried out in accordance with a modified version of Belzona® Know-How Leaflet RPA-8

BELZONA FACTS

Sealing with Belzona® 3111 Flexible Membrane has eliminated the annual maintenance required to ensure that the corrosion was kept in check. This application has been in service for 6 years with no additional maintenance requirements.

PHOTOGRAPHS

1. View of corrosion problem
2. Application of Belzona® 3111 Flexible Membrane in progress.
3. Completed application

