
BELZONA® 3000 SERIES PRODUCTS SOLVE CORROSION PROBLEM

CUSTOMER

Swimming Pool
Trail, BC

APPLICATION DATE

May 2006

PROBLEM

Condensation was settling on various parts of the pipe hanger brackets causing them to corrode and thus creating an unsightly visual problem as well as leaving rust stains on the floor area beneath them .

PRODUCTS

Belzona® 3111 Flexible Membrane
Belzona® 3921 GSC Conditioner

SUBSTRATE

steel

APPLICATION METHOD

Application carried out in accordance with a modified version of Belzona® Know-How Leaflet RPA-1

BELZONA FACTS

Sealing the hanger brackets in this way prevents water from getting underneath the metal hangers and stops the corrosion problem.

PHOTOGRAPHS

1. View of one of the problem areas
2. Preparation of the area underway.
3. Completed application

