
BELZONA® SEALS EXPANSION JOINTS IN CLARIFIER

CUSTOMER

PULP AND PAPER COMPANY
Skookumchuck, BC

APPLICATION DATE

August 2002

PROBLEM

Original caulking material had failed creating an environmental seepage hazard.

PRODUCTS

Belzona® 2211 MP Hi-Build Elastomer
Belzona® 2221 MP Fluid Elastomer
Belzona® 4111 Magma Quartz

SUBSTRATE

Concrete

APPLICATION METHOD

Application carried out in accordance with Belzona® Know-How Leaflet FPA-6

BELZONA FACTS

The use of Belzona products allowed the mill rebuild damaged concrete and replace the 1200 feet of expansion joint material with a minimum amount of delay.

PHOTOGRAPHS

1. View of application in progress with product on site.
2. View of clarifier with some 1200ft of expansion joints.
3. Application in progress

